

V20-72-9991 CONTROL UNIT, PARK ASSIST SENSOR

23902

Control unit



Indications for a defect

The following signs indicate a defect of the PDC sensors:

- × permanent tone after engaging the reverse gear when no barrier is recognizable
- × no acoustic signal despite recognizable barriers
- × soft „humming“, even though there is no barrier
- × flashing of several warning lights

The most common cause of a defect is moisture. Because the control unit for PDC sensors is located below the trunk, moisture can accumulate there as a result of leakages of the bodywork. This can cause the system failure.



BMW E81, E82, E84, E87, E88, E90, E91, E92, E93

X-Ref: 66 20 9 252 639
66 21 6 947 796
66 20 9 225 825

V20-72-9991

For further information visit www.autoteile.de