


BLOWER CONTROL UNIT

25202

**FORD COUGAR, FOCUS, MONDESO, TRANSIT****X-Ref**

1 311 115
1 110 969
1 066 902

V25-79-0007

Especially in the cold season, clouded glasses are a common problem. Caused by the interplay of high humidity and cold temperatures, this effect quickly develops into a safety problem.

To get a clear view for safe driving within a few seconds, a perfectly working blower is an indispensable necessity. If this is not the case, it might not always depend on the interior blower itself. Often a fault blower control is responsible for a limited function of the blower speed 1 to 3.