



REPAIR SET, CYLINDER HEAD COVER V10-4149 | 06D 103 469 N KIT1* & V10-4152 | 06D 103 469 N KIT2*

AIR CONTROL SYSTEMS | 11103



RECOMMENDED BY THE EXPERTS

· Please To avoid those problems, please always replace the cylinder head cover, the matched oil separator and hoses.





CDCC, CDLF, CDLG, CRZA, CDLA, CDLD

REPAIR SET, CYLINDER HEAD COVER

WITH THROTTLE VALVE



Engine Code	CDCC, CDLF, CDLG, CRZA, CDLA, CDLD		
Audi	A3, A4, A6		
Seat	Leon, Altea		
VW	Golf V, Passat		
Parts list	1x cylinder head cover	06D 103 469 N*	V10-3868
	1x oil separator	06F 129 101 N*	V10-9732
	1x gasket	06F 103 483 E*	V10-2559
	4x screws	N 104 128 04*	V10-3245
	1x hose	06F 103 235*	V10-2779
	1x hose	06F 103 221 E*	V10-0775
Engine Type	Petrol		
X-Ref			
06D 103 469 N kit1*		V10-4149	

BPY, BWA, BPJ, BYIK

REPAIR SET, CYLINDER HEAD COVER

WITHOUT THROTTLE VALVE



V10-3868	
V10-9751	
V10-2559	
V10-3245	
V10-2779	
V10-0775	
V10-4152	
(

For detailed vehicle information, please refer to the vehicle lists under www.autoteile.de.

Notes: Temporary offers are only valid while stocks last. All offers remain subject to prior sale. Our general terms and conditions of sale and delivery as well as our warranty conditions apply, which are available for download on our website. All prices are net prices. Errors excepted. Reference numbers and names, with the exception of VIEROL AG, are for comparison only and may not be disclosed in invoices. They are non-binding and no indication of origin. © VIEROL AG